

dangerous moving part of a machine; (b) a pinch point, cutting edge or point of a machine at which material is cut, shaped, bored or formed;

146. (1) If the conditions described in subsection (2) apply, an employer shall install (a) an audible alarm system that provides a warning of sufficient volume and for a sufficient period before start-up of the machine to give workers timely notice of the imminent start up.

Recommendations to Prevent Recurrence

- Ensure that all employees are instructed in the use of automated garage door use.
- Position the operational controls at a position where the operator cannot come into contact with moving parts.
- Ensure controls have a fail-safe mechanism (i.e. a dead man's switch).
- Install audible/visible alarms to alert workers when the garage door is opening and closing.
- Ensure (if installed) the safety devices installed on the garage door are functioning and operational.